INCIDENT COMMAND BRIEFING

12 Foundry Row

Mount Dinham area, Exeter

12 Foundry Row — Developing fire — day · kitchen fire

TURNOUT SHEET — FROM FIRE CONTROL

INCIDENT	Building fire — developing
LOCATION	Mount Dinham area, Exeter
REPORTED	smoke and flames showing
ATTENDANCE	2 pumps mobilised

ON ARRIVAL — FIRST VIEW FROM THE STREET

WHAT YOU CAN SEE

- Fire developing — flames showing from the opening.
- Grey smoke, steady, hot.
- Wind pushing the plume to the right (strength 20/100).
- Compartment closed up — treat as ventilation-limited.
- Daylight.

PREMISES — MDT / SSRI

BUILDING	not recorded
RISK TYPE	domestic
PLAN	Floor plan held — see property record
NOTES	Victorian terrace, single staircase, parked cars restrict appliance access.

AI-generated training material — not a real incident. Produced with FireScene for exercise use only.

INSTRUCTOR COPY

DO NOT ISSUE TO CANDIDATES — these facts must be earned by the right order

AUTHORED CONDITIONS

Severity 40/100 · stage developing · smoke grey 35/100 (hot)
Ventilation sealed · wind 20/100 to the right · day, clear
Tags: terraced, domestic, starter-pack

PROPERTY NOTES

Victorian terrace, single staircase, parked cars restrict appliance access.

AI-generated training material — not a real incident. Produced with FireScene for exercise use only.