

INCIDENT COMMAND BRIEFING

Rose Cottage

Badminton, Gloucestershire

Rose Cottage — Incipient fire — day

TURNOUT SHEET — FROM FIRE CONTROL

INCIDENT	Fire — small fire in a building
LOCATION	Badminton, Gloucestershire
REPORTED	smoke and flames showing
ATTENDANCE	1 pump mobilised

ON ARRIVAL — FIRST VIEW FROM THE STREET



WHAT YOU CAN SEE

- Fire developing — flames showing from the opening.
- Brown smoke, steady, hot.
- Wind pushing the plume to the right (strength 10/100).
- Openings ventilated.
- Daylight.

PREMISES — MDT / SSRI

BUILDING	not recorded
RISK TYPE	heritage / thatch
PLAN	Floor plan held — see property record
NOTES	Thatched roof, timber frame; nearest hydrant 400m — water relay likely.

DO NOT ISSUE TO CANDIDATES — these facts must be earned by the right order

AUTHORED CONDITIONS

Severity 40/100 · stage incipient · smoke brown 35/100 (hot)
Ventilation ventilated · wind 10/100 to the right · day, clear
Tags: thatch, heritage, rural, starter-pack

PROPERTY NOTES

Thatched roof, timber frame; nearest hydrant 400m — water relay likely.