INCIDENT COMMAND BRIEFING

St Mary's Primary

School Road, Milltown

St Mary's Primary — Fully developed fire — day · fully involved

TURNOUT SHEET — FROM FIRE CONTROL

INCIDENT	Fire in an education premises
LOCATION	School Road, Milltown
REPORTED	well alight, flames showing; pupils or staff may still be inside
ATTENDANCE	3 pumps mobilised

ON ARRIVAL — FIRST VIEW FROM THE STREET

WHAT YOU CAN SEE

- Well alight — flames from the opening and making up.
- Dark smoke, heavy, hot.
- Wind pushing the plume to the right (strength 20/100).
- Openings ventilated.
- Daylight.

PREMISES — MDT / SSRI

BUILDING	School
RISK TYPE	education
PLAN	Floor plan held — see property record
NOTES	Stone village school, daytime occupancy 240 pupils. Evacuation point: playing field.

INSTRUCTOR COPY

DO NOT ISSUE TO CANDIDATES — these facts must be earned by the right order

AUTHORED CONDITIONS

Severity 80/100 · stage fully-developed · smoke dark 75/100 (hot)
Ventilation ventilated · wind 20/100 to the right · day, clear
Tags: school, public-building, starter-pack

PROPERTY NOTES

Stone village school, daytime occupancy 240 pupils. Evacuation point: playing field.

AI-generated training material — not a real incident. Produced with FireScene for exercise use only.