

St Mary's Primary

School Road, Milltown
St Mary's Primary — Developing fire — day · classroom developing

TURNOUT SHEET — FROM FIRE CONTROL

INCIDENT	Fire in an education premises
LOCATION	School Road, Milltown
REPORTED	smoke and flames showing; pupils or staff may still be inside
ATTENDANCE	3 pumps mobilised

ON ARRIVAL — FIRST VIEW FROM THE STREET



WHAT YOU CAN SEE	PREMISES — MDT / SSRI	
<ul style="list-style-type: none">Fire developing — flames showing from the opening.Grey smoke, steady, hot.Wind pushing the plume to the right (strength 20/100).Openings ventilated.Daylight.	BUILDING	School
	RISK TYPE	education
	PLAN	Floor plan held — see property record
	NOTES	Stone village school, daytime occupancy 240 pupils. Evacuation point: playing field.

INSTRUCTOR COPY

DO NOT ISSUE TO CANDIDATES — these facts must be earned by the right order

AUTHORED CONDITIONS

Severity 55/100 · stage developing · smoke grey 55/100 (hot)

Ventilation ventilated · wind 20/100 to the right · day, clear

Tags: school, public-building, starter-pack

PROPERTY NOTES

Stone village school, daytime occupancy 240 pupils. Evacuation point: playing field.