

12 Foundry Row

Mount Dinham area, Exeter
12 Foundry Row — Incipient fire — day · first crew on scene

TURNOUT SHEET — FROM FIRE CONTROL

INCIDENT	Fire — small fire in a building
LOCATION	Mount Dinham area, Exeter
REPORTED	smoke issuing
ATTENDANCE	1 pump mobilised

ON ARRIVAL — FIRST VIEW FROM THE STREET



AI-GENERATED · FIRESCE TRAINING MATERIAL · NOT A REAL INCIDENT

WHAT YOU CAN SEE	PREMISES — MDT / SSRI	
<ul style="list-style-type: none">• Small fire — smoke issuing, little flame visible from the street.• Light smoke, light, cool and lazy.• Wind pushing the plume to the right (strength 20/100).• Openings ventilated.• Daylight.	BUILDING	not recorded
	RISK TYPE	domestic
	PLAN	Floor plan held — see property record
	NOTES	Victorian terrace, single staircase, parked cars restrict appliance access.

DO NOT ISSUE TO CANDIDATES — these facts must be earned by the right order

AUTHORED CONDITIONS

Severity 25/100 · stage incipient · smoke light 25/100 (cold)
Ventilation ventilated · wind 20/100 to the right · day, clear
Tags: terraced, domestic, starter-pack

PROPERTY NOTES

Victorian terrace, single staircase, parked cars restrict appliance access.