INCIDENT COMMAND BRIEFING

12 Foundry Row

Mount Dinham area, Exeter

12 Foundry Row — Fully developed fire — day · well alight

TURNOUT SHEET — FROM FIRE CONTROL

INCIDENT	Building fire — well alight, making up
LOCATION	Mount Dinham area, Exeter
REPORTED	well alight, flames showing; persons reported
ATTENDANCE	4 pumps and an aerial ladder platform mobilised

ON ARRIVAL — FIRST VIEW FROM THE STREET

WHAT YOU CAN SEE

- Well alight — flames from the opening and making up.
- Black smoke, heavy, hot.
- Wind pushing the plume to the right (strength 30/100).
- Openings ventilated.
- Daylight.

PREMISES — MDT / SSRI

BUILDING	not recorded
RISK TYPE	domestic
PLAN	Floor plan held — see property record
NOTES	Victorian terrace, single staircase, parked cars restrict appliance access.

AI-generated training material — not a real incident. Produced with FireScene for exercise use only.

INSTRUCTOR COPY

DO NOT ISSUE TO CANDIDATES — these facts must be earned by the right order

AUTHORED CONDITIONS

Severity 90/100 · stage fully-developed · smoke black 85/100 (hot)
Ventilation ventilated · wind 30/100 to the right · day, clear
Tags: terraced, domestic, starter-pack

PROPERTY NOTES

Victorian terrace, single staircase, parked cars restrict appliance access.

AI-generated training material — not a real incident. Produced with FireScene for exercise use only.